

# Removing Manual Geometry Transformations

The following steps outline the process to clear the 3D scene from all manual geometry transformations:

1. Right-click anywhere on the 3D scene and click **Reset View**.
2. All 3D CAD models will be set to their default orientations and sizes on the 3D scene, and unsaved manual geometry transformations will be lost and cannot be restored.

